



TYPE 12 Thermocouple — Stick Probe



Weld straps are available — add suffix "H" to P/N followed by quantity required.



Will be furnished with radius if applicable pipe size is given.

LINE #	SENSOR		TYPE	# OF WIRES	SHEATH MATERIAL	MEASURING JUNCTION	OPTIONS
	(WIRE GA)	SHEATH DIAMETER					
1	(20)	3/16	J		316 SS	GROUNDED	* COMPRESSION FITTING
2	(18)	1/4	K	2	INC.	UNGROUNDED	▲ BRAZED ON BUSHING
3	(16)	5/16	E		OTHER ADVISE	EXPOSED	WELD PAD
4	OTHER ADVISE		T	4			

P/N 12 —

--	--	--	--	--	--	--	--

Complete using the line number for each column in sequence from left to right. Specify: Dimensions "L" and "X".

* Specify: Material, NPT, and type ferrule (Teflon for readjustment, metal for fixed position). See pages 22, 23.

▲ Specify: Material, NPT, location and thread mounting direction

* If sleeving required, specify material.

