


TYPE 14 -250 to 550°C RTD



LINE NO.	SENSOR				OPTIONS
	DIA.	TYPE	NO. OF LEADS	SHEATH MAT'L	
1	1/4	100 Ω PLAT.	6	316 SS	* COMPRESSION FITTING
2	3/16	OTHER ADVISE	2	347 SS	▲ BRAZED ON BUSHING
3	1/8		3	OTHER ADVISE	
4			4		

P/N 14

--	--	--	--	--	--

Complete using the line number for each column in sequence from left to right. Specify: Dimensions "L" and "X".

- * Specify: Material, NPT, and type ferrule (Teflon for readjustment, metal for fixed position) – see pg. 22
- ▲ Specify: Material, NPT, location and thread mounting direction

